



Technische Daten der SEUTHE-Dampfgeneratoren

| Art.-Nr. | Abb. | Betriebsspannung von - bis V ≈ | Stromaufnahme ca. mA | Anschlussdrähte |
|----------|------|--------------------------------|----------------------|-----------------|
| 3 - 14 | - | 8 - 14 | 140 | 2 |
| 4 | 1 | 3 - 4 | 500 | 2 |
| 5 | 1 | 4,5 - 6 | 260 | 2 |
| 6 | 1 | 10 - 14 | 140 | 2 |
| 7 | 1 | 11 - 16 | 140 | 2 |
| 8 | 1 | 16 - 22 | 100 | 2 |
| 9 | 2 | 8 - 14 | 140 | Steck- |
| 10 | 2 | 10 - 16 | 130 | Dampf- |
| 11 | 2 | 16 - 22 | 70 | Generator |
| 12 | 2 | 16 - 22 | 70 | 2 |
| 99 | 2 | 8 - 14 | 140 | 2 |
| 100 | 2 | 10 - 16 | 120 | 2 |
| 20 | 3 | 10 - 16 | 120 | Steck-Dampf- |
| 24 | 3 | 16 - 22 | 70 | Generator |
| 21 | 3 | 10 - 16 | 120 | 1 |
| 22 | 4 | 10 - 16 | 120 | 2 |
| 23 | 4 | 16 - 22 | 70 | 2 |
| 27 | 7 | 10 - 16 | 120 | 2 |
| 28 | 7 | 16 - 22 | 70 | 2 |
| 117 | 5 | 16 - 18 | 50 | 2 |
| 490 | 6 | 6 - 7 | 800 | 2 |
| 491 | 6 | 6 - 7 | 800 | 2 |
| 500 | 6 | 8 - 12 | 700 | 2 |
| 501 | 6 | 8 - 12 | 700 | 2 |
| 503 | 6 | 10 - 16 | 350 | 2 |
| 600 | 8 | 12 | 1700 | 2 |
| 601 | - | 4 - 12 | | 2 |

Maße in mm

